```
Index
                                            CORNER RECORD (SEARCH) '
                                                                       Tract or
                                                                                                   93.
                                                                                         Cor.
File No. X-22
                                            Ref. FSM 7151.4
                                                                       Survey No
                                                                                         No.
T65
                  R32E
                                    R.D.
                                            North Fork John Day
                                                                       County Umatilla
Merid. Willamette
                                    Ń.F.
                                            Umatilla
                                                                       State
                                                                                Oregon
Corner Diagram
                                   I Describe corner monument found
                        H---
                                    1 Standard BLM brass cap stamped as shown in the corner diagram.
                       C --- C
                       S36
                       1968
Photo Identification Data
                                   l Describe bearing trees or other official accessories found
Photo No.
                                   1 A 9" Ponderosa Pine bears S2 E, 7.9' with the top recently broken out.
filed at
                                   l A 13" Ponderosa Pine bears N17 1/2 W, 22.5' with partially visible scribing.
Object Ident.
Ident. by
                 Signature
Plane Coordinate Position Data
                                   1 Describe corner location relative to near-by features, also how to reach corner
State
                 Zone
                                   1 From the junction of roads 55 and 5507, follow road 5507 southeast 1.7
                                   l miles to road 175. Follow road 175 0.4 miles to a point 120' before the fence
                                   l crossing of the road. Follow the posted line east 500' to the corner.
Estab. by
                 Agency
        Signature
                          Title
                                           Division
                                                             Headquarters
                                                                                       Date
                                                                                                  7100.52
David L. Haddwell Land Surveyor
                                                             Pendleton, OR
                                                                                       July 1988
```

nanw_Lnkeal aekalre

CORNER RECORD (PERPETUATION)

Monument: Describe new monument set, or work done to preserve existing monument

Set steel guard post 5' west of the monument and attached Forest Service Land Survey Monument and Property Boundary signs.

Established a new bearing tree. This tree is a 9" Ponderosa Pine which bears \$20 1/2 E, 11.4' from the corner. Scribed this tree CW1/16 \$36 BT and nailed an aluminum washer stamped RLS 852 between the letters B and T. Made bands around all three trees and painted the bands and the scribe blazes red. Attached Forest Service Land Survey Monument and Bearing Tree signs to each tree.

X
State Registration No.

Work done by David L. Haddock Title Land Surveyor Date July 1988 or Agency 852
Certified cor. record prepared? yes x no Filed at Pendleton, OR Date August 1988
x
x

REMARKS

V-11 TIS DADE, WM