USDA-FOREST SERVICE INDEX FILE NOC-15 T7 SR32 E MeridWillagette	CORNER RECORD (SEARCH) (Ref. FSM 7151.4) R.DNorth Fork John Day N.FUMATILLA	County Grant	No	Cor. No.	
CORNER DIAGRAM 1	l DESCRIBE CORNER MONUMENT FO l Found standard BLM brass ca l l	p stamped as shown			2
PHOTO IDENTIFICATION DATA Photo No. Filed at. Object Ident. Ident. By Signature	l DESCRIBE BEARING TREES OR DI 	HER OFFICIAL ACCE	SSORIES FOUND		3
x Y	1 DESCRIBE CORNER LOCATION REL 1 Follow FSR 55 from Highway 3 1 and turn west after 100 yard 1 up a steep grade for 0.6 mil 1 wood section line post. From 1 to the corner.	95 to FSR 5505. Fo s. Follow this pri me to a Junction. F	llow FSR 5505 2 mi mitive road 1 mile ollow the south for	les. Cross a ca around a steep	attle guard o hill and then
Signature Titi David L. Haddock Surv	le Division veyor	Headquarters Péndleton, OR	Date FS-7100- 2-15-94	-52 (3/68)	· 5

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Cleared brush and debris away from corner.	
ACCESSORIES: DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Set new bearing trees. A 7" dbh Douglas Fir bears NO 3/4°E, 24.8' scribed C1/4 S3 BT. A 7" dbh Douglas Fir bears N28 1/4°E, 27.0' scribed C1/4 S3 BT. A 18" dbh Douglas Fir bears S54°W, 23.8' scribed C1/4 S3 BT. An aluminum washer stamped RLS 852 is nailed between the letters B and T on each new tree. BT and LSM attached to each bearing tree. Six inch red bands are painted around each bearing tree and the blazes are painted red.	
State Registration No. Hork Dene ByDavid L. HaddockTitle_Land SurveyorDate_9-21-93or AgencyPLS 852	

. Index File No. C-15 T. 7 S. R. 32 E. M. Willamette Tract or Surv. No. 13 €or.

GPO: 1984 D - 439-095

USDA-FOREST SERVICE	• •	
Index File No C-1.5	CORNER RECORD (SEARCH) Tract or Cor. N. Fk. (Ref. FSM 7151.4) Survey No No	
T <u>78</u> R. <u>32E</u>	R.D. John Day County Grant	
Merid. W.M.	N.F. Umatilla State Or	 -
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	<u>1</u>
1	2½" iron pipe with 3½" brass cap (BLM) C½ S3 1968	E
N C1 83		
· · ·	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	<u>2</u>
	D. Fir, 12", $584\cancel{1}^{\circ}$ E, $86\cancel{1}$ lks.; with healed blaze. D. Fir, 6", 850° W, $7\cancel{1}$ lks.; scribing visible.	•
PHOTO IDENTIFICATION DATA		
Photo No.		
Filed At.		
Object ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORN	3
Ident. By		
Signature 7	Corner falls on steep Wly slope, E. of cr. Posted	
PLANE COORDINATE POSITION DATA	line to W.	,
State Zone		
× —		-
Fatab Bu		
Estab. By		
Signature F/ Muns	Title Division Headquarters Date FS-7100-52 (3/6) PLS $7/11/90$	4 58) 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT None..

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE None.

		** •			•	-	
Work Done By.	F.S. Munro	Title	PLS	7/7/90	State Registration No. or Agency	1832	
Certified Cor.	Record Prepared ? Yes	No X Fil	ed At:		Date		

Cor.

32E GPO: 1984 O. - 439-095

Index File No.

0-15 T 78

Tract or Surv. No.