Exteriors of T. 1 N., R. 298E. Surveyed by David P. Thompson under contract No. 83. Dated July 22, 1859.

-

	Chains	I commenced at the estavlished corner to Townships 1,
		North of Ranges 28 and 29 East on the Base Line.
		North between secs. 31 and 36.
)	40.00	Set post for $\frac{1}{4}$ sec. corner in mound of stone.
	80.00	Set post for corner to secs. 30, 31, 25, and 36 in mound
		of Earth &c as per instructions.
		Land, rough and broken.
		Soil, 3rd rate.
		North between secs. 25 and 30.
		Var. 18° East.
	40.00	Set post for $\frac{1}{4}$ sec. corner in mound of Earth &c as per
		instructions.
	65.70	Butter Creek, 20 1ks. wide, runs N.W., bottom about 500
		lks. wide.
)	80.00	Set post for corner to secs. 24, 25, 19 and 30 in mound of
j		Earth &c as per instructions.
		Land, rough and broken, stony.
		Soil, 3rd rate.
		North between secs. 19 and 24.
		Var. 18° 30' East.
	40.00	Set post for $\frac{1}{4}$ sec. corner in mound of Earth &c as per
		instructions.
2	80.00	Set post for corner to secs. 18, 19, 13 and 24 in mound of
	1 E.	Earth &c as per instructions.
		Land, gently rolling.
	1. u. 80	Soil, good, 2nd rate.
2		North between secs. 13 and 18.
		Var. 19° 30' East.
	40.00	Set post for $\frac{1}{4}$ sec. corner in mound of Earth &c as per
		instructions.
	80.00	Set post for corner to secs. 12, 13, 7 and 18 in mound
	00.00	A REAL PROPERTY REPORTED AND A REAL AND
		of Earth &c as per instructions.

3

4

C

KILJUM 156741